### **GOVERNMENT OF INDIA** MINISTRY OF CIVIL AVIATION

RAJYA SABHA UNSTARRED QUESTION NO: 482 (TO BE ANSWERED ON THE 12<sup>th</sup> December 2022)

#### SAFETY STANDARD MEASURES BY DGCA

#### 482. SHRI M. MOHAMED ABDULLA

Will the Minister of CIVIL AVIATION be pleased to state:-

- (a) whether the Directorate General of Civil Aviation (DGCA) has taken any proactive measures to ensure maintenance of the highest level of safety standards by the airlines;
- (b) if so, the details thereof; and
- (c) the number of non-compliances recorded from January 2021 and the details about the appropriate enforcement action taken against them by DGCA?

#### **ANSWER**

#### MINISTER OF STATE IN THE MINISTRY OF CIVIL AVIATION

(GEN. (DR) V. K. SINGH (RETD))

- (a) & (b) Directorate General of Civil Aviation (DGCA) has a laid down mechanism of conducting surveillance, spot checks, night surveillance etc. of the airlines to ensure safety of passenger and aircraft. The observations/ findings made during surveillance, spot checks and night surveillance are provided to the airline for taking corrective action. The action taken to correct the observations are reviewed and the findings closed. All occurrences are mandatorily reported to DGCA. These occurrences are thoroughly analysed and severity is determined. Based on severity, these occurrences are investigated. Appropriate action is taken on the outcome of investigation. In addition, special audits are also carried out as per the risk perceived. Based on the violations found during surveillance, spot checks, night surveillance, DGCA initiates enforcement action against the airlines/operator as per the procedure given in Enforcement policy and Procedures Manual (EPPM) which includes warning, suspension, cancellation of approval/ licence including imposition of financial penalty on the personnel involved/ airline.
- (c) List of the notices/ enforcement action taken on engineering and maintenance aspects from January 2021 to October 2022 is enclosed as Annexure A.

# <u>DETAILS OF ENFORCEMENT ACTION TAKEN BY AIRWORTHINESS DIRECTORATE (YEAR 2021-2022)</u>

## 'Annexure-A'

S.NO	Operator	Detail of Violation	Action Taken
2021			
1.	M/s Horizon	Failed to discharge the duties and responsibilities as an	Warning Issued
	Aerospace India Pvt.	Accountable Manager in accordance with CAR 145.	J
	Ltd.	, and the second	
2.	M/s InterGlobe	ARC has been extended when the aircraft is under major	Form-4 has been
	Aviation Ltd.	maintenance and both the engines were removed.	withdrawn
3.	M/s AR Airways Pvt. Ltd.	One Time authorisation issued by Dy. QM without ensuring License requirements.	Warning Issued
4.	M/s AR Airways Pvt. Ltd.	Failed to discharge the duties and responsibilities as continuing Airworthiness Manager.	Warning Issued
5.	M/s Pinnacle Air Pvt. Ltd.	Failed to discharge the duties and responsibilities of continuing Airworthiness Manager as defined in CAME.	Warning Letter
6.	M/s Pinacle Air Pvt	Failed to discharge the duties and responsibilities as an	Warning Letter
0.	Limited	Accountable Manager in accordance with CAR-M.	
7.	M/s SPICE JET	AMM procedure not followed while carrying out the maintenance on aircraft.	Warning Letter
8.	M/s GVHL	Irregularity in OJT task certification.	Warning Letter
9.	M/s GVHL	Failed to discharge the duties and responsibilities while issuance of certification Authorisation.	Warning Letter
10.	M/s Patiala Aviation Club	Irregularity found during releasing the aircraft and Fuel upliftment.	License suspended for Six month.
11.	M/s Patiala Aviation	Failed to discharge the duties and responsibilities as an	Warning Letter
12.		Accountable Manager Violated sub -rule 15 of rule 61 of the aircraft rules,1937	Warning Letter
12.	Services Pvt. Ltd	Violated Sub-rule 15 of fule of of the all chart fules, 1957	Waiting Letter
13.	M/s Yatih Air Services Pvt. Ltd	violated sub -rule 10 of rule 133B of the aircraft rules,1937	Warning Letter
14.	M/s Yatih Air Services Pvt. Ltd	Violated sub -rule 15 of rule 61 of the aircraft rules,1937.	Warning Letter
15.	M/s GVHL	Irregularity in OJT task certification.	Warning Letter
16.	M/s Patiala Aviation Club	Failed to discharge the duties and responsibilities as Quality Manager	Warning Letter
022	Cias	- Manager	
1.	M/s AR Airways	Not ensured the approval status of the maintenance location	Form 4 has been
2.	M/s AR Airways	while releasing the aircraft.  Performance of Maintenance at unapproved location and	Withdrawn Form 4 has been
	•	released the aircraft.	Withdrawn.
3.	M/S TATA SIA (Vistara)	Failed in Breath-analyzer Test.	License suspended for 1 year.
4.	M/s Redbird Aviation Academy Pvt. Ltd.	Failed to discharge the duties and responsibilities as accountable Manager	Warning Letter
5.	M/s The Bombay	Failed to discharge the duties and responsibilities as	Warning Letter
J.	Flying Club	accountable Manager	, and the second
6.	M/s Indamer Aviation Pvt Ltd	AMM procedure not followed while carrying out the maintenance on aircraft.	Warning Letter
7.	M/s Indamer Aviation Pvt Ltd	AMM procedure not followed while carrying out the maintenance on aircraft.	License suspended for 3 month
8.	M/s Indamer Aviation	AMM procedure not followed while carrying out the	Warning Letter
	Pvt Ltd	maintenance on aircraft.	
9.	M/s Go Airlines (I) Ltd.	wrongly replaced "Loop B (AGB and Core) instead of faulty Loop A and due to perfunctory maintenance or component	Warning Letter
		being faulty, the Loop B had generated a faulty signal.	
10.	M/s Go Airlines (I)	wrongly replaced "Loop B (AGB and Core) instead of faulty	Warning Letter
	Ltd.		

		Loop A and due to perfunctory maintenance or component being faulty, the Loop B had	
11.	M/s Go Airlines (I)	generated a faulty signal.  wrongly replaced "Loop B (AGB and Core) instead of faulty	Warning Letter
'''	Ltd.	Loop A and due to perfunctory maintenance or component	vvairiing Letter
	Ltd.	being faulty, the Loop B had	
		generated a faulty signal.	
12.	M/s Go Airlines (I)	wrongly replaced "Loop B (AGB and Core) instead of faulty	Warning Letter
	Ltd.	Loop A and due to perfunctory maintenance or component	
		being faulty, the Loop B had	
		generated a faulty signal.	
13.	M/s Go Airlines (I)	not effectively discharged his duties and responsibilities as	Warning Letter
	Ltd.	defined in associated manual (EPM) of approved CAME.	
14.	M/s GVHL	Mr. Delet Wesser Mister AME Liver No 0004 to 4 44	License supponded
14.	IVI/S GVAL	Mr. Rajesh Kumar Mishra, AME Licence No.9664 has tested breath-analyzer positive for second time on 29-03-2022 at juhu	License suspended for 1 year
		mumbai.	loi i yeai
15.	M/s National Flying	Failed to discharge the duties and responsibilities as Quality	Form 4 has been
10.	Training Institute,	Manager (QM)	Withdrawn - QM
	Gondia	Manager (QIVI)	
16.	M/s National Flying	Failed to discharge the duties and responsibilities as	Form 4 has been
	Training Institute,	Maintenance Manager (MM)	Withdrawn - MM
17.	Gondia M/s National Flying	Failed to discharge the duties and responsibilities as	Imposed a penalty
17.	Training Institute,	Accountable Manager	on Mls National
	Gondia	Accountable Manager	flying Training
			Organisation,
			Gondia of Rupees
			7,50,000/- (Rupees
			Seven Lakh Fifty Thousand only)
18.	M/s Academy of	Failed to discharge the duties and responsibilities as Training	Financial Penalty of
	Aviation and	Manager	Rs 75000
	Engineering		
19.	M/s Academy of	Failed to discharge the duties and responsibilities as	Counselling Letter
	Aviation and	Accountable Manager	issued to the Accountable
	Engineering		Manager
20.	M/s Spicejet	Aircraft VT-SZM after operating on Sector IXZ-MAA, was not	orally counselled
	The state of the s	attended to upon arrival at 12:48 Hrs (IST) by any AME.	,
21.	M/s Spicejet	Aircraft VT-SZM after operating on Sector IXZ-MAA, was not	orally counselled
		attended to upon arrival at 12:48 Hrs (IST) by any AME.	
22.	M/s Spicejet	Aircraft VT-SZM after operating on Sector IXZ-MAA, was not	orally counselled
	251 51 5	attended to upon arrival at 12:48 Hrs (IST) by any AME.	
23.	M/s Spicejet	Aircraft VT-SZM after operating on Sector IXZ-MAA, was not	orally counselled
24.	M/a Spingiet	attended to upon arrival at 12:48 Hrs (IST) by any AME.	omolly, ocumented
24.	M/s Spicejet	Aircraft VT-SZM after operating on Sector IXZ-MAA, was not attended to upon arrival at 12:48 Hrs (IST) by any AME.	orally counselled
25.	M/s Alliance Air	CAMO FAILURE	Warning Letter
20.	W/O / tilidride / til	CHWO THEORE	issued to
			Accountable
			Manager
26.	M/s Jet Serve	Line maintenance work was carried out at unapproved location.	Warning Letter
	Aviation Pvt. Ltd.		issued to Accountable
			Manager
27.	M/s SAR Aviation	CAM & QM had resigned from organisation and no intimation	Warning Letter
		was given to DGCA nor a new post holder proposed.	issued to
			Accountable
			Manager & CAMO
			approval has been
			kept in abeyance till the organisation
			meets the
			requirements.
28.	M/S SPICE JET	AMM procedure not followed while carrying out the	Lic suspended for 3

	LTD.	maintenance on aircraft.	month
29.	M/S SPICE JET LTD.	AMM procedure not followed while carrying out the maintenance on aircraft.	Lic suspended for 3 month
30.	M/S SPICE JET LTD.	AMM procedure not followed while carrying out the maintenance on aircraft.	Warning Letter
31.	M/S SPICE JET LTD.	AMM procedure not followed while carrying out the maintenance on aircraft.	Warning Letter
32.	M/S SPICE JET LTD.	AMM procedure not followed while carrying out the maintenance on aircraft.	Warning Letter
33.	M/s Alchemist Aviation Pvt. Ltd. (Jamshedpur)	Failed to discharge the duties and responsibilities as Accountable Manager	Warning Lettter
34.	M/s GATI (Bhubaneswar)	Failed to discharge the duties and responsibilities as Accountable Manager	Warning Lettter
35.	M/s Bharat Petroleum Corporation Limited	Failed to discharge the duties and responsibilities as Dy QCM	Counselling of Dy QCM