### GOVERNMENT OF INDIA MINISTRY OF ENVIRONMENT, FOREST AND CLIMATE CHANGE

### RAJYA SABHA UNSTARRED QUESTION NO.1486 TO BE ANSWERED ON 24.12.2018

### Impact of cyclone 'Gaja' on Point Calimere Bird Sanctuary, Nagapattinam

1486. SHRI ANAND SHARMA:

Will the Minister of ENVIRONMENT, FOREST AND CLIMATE CHANGE be pleased to state:

- (a) whether it is a fact that the Cyclone 'Gaja' in Tamil Nadu has badly damaged Point Calimere Bird Sanctuary at Nagapattinam district, killing thousands of birds and wildlife besides affecting flora and fauna;
- (b) if so, the details thereof;
- (c) whether any study has been conducted to assess the extent of damage to the sanctuary, if so, the details thereof; and
- (d) measures proposed by Government to repair the damage to the coastal sanctuary?

#### **ANSWER**

# MINISTER OF STATE IN THE MINISTRY OF ENVIRONMENT, FOREST AND CLIMATE CHANGE (DR. MAHESH SHARMA)

(a) and (b) As informed by the State Government of Tamil Nadu, 'GAJA' Cyclone had a huge impact in the Vedaranyam area, where Point Calimere Wildlife Sanctuary exists. The infrastructure of the Wildlife Sanctuary suffered the most with the Interpretation Centres, Forest Guest houses, Entry Gate, Compound walls etc. badly damaged.

As far as flora and fauna is concerned, the impact of the cyclone was marginal. State Government has recorded death of 710 birds from the Vedaranyam area. Further, 26 animal deaths have also been recorded in the aftermath of the cyclone. Details of the animal death are given below:

| S.No. | Name of the dead animal | Nos. |
|-------|-------------------------|------|
| 1.    | Black buck              | 21   |
| 2.    | Spotted Deer            | 1    |
| 3.    | Wild boar               | 4    |
|       | Total                   | 26   |

- Yes, Sir. The State Government has conducted study to assess the extent of damage to the sanctuary. Details are given in the **Annexure I.**
- (d) As informed by the State Government, following measures are proposed to be taken:
  - i. Rehabilitation works for infrastructure in the Sanctuary.
  - ii. Rehabilitation works for vegetation in the Sanctuary.

### **ANNEXURE**

## NAGAPATTINAM DIVISION

## (Rs.in Lakhs)

| SI.<br>No. | Range<br>2  | Name of<br>Building  | Year of<br>Const-<br>ruction<br>4 | Present usage  | Details of damages   | Amount required for renovation |
|------------|-------------|--|-----------------------------------|--|--|--------------------------------|
| 1)         | Vedharanyam | Ramarpatham<br>steps and Safety<br>wall  | 2006                              | Mythological place<br>and important for<br>eco-tourism   | Steps damaged and No protection around the main sanctum                                      | 5.00                           |
| 2)         | Vedharanyam | Ramarpadham<br>watch tower   | 2006                              | Crucial Watch Tower<br>to mitigate Poaching<br>Activities in<br>Sanctuary                      | Major Part of Watch<br>Tower is damaged  | 5.00                           |
| 3)         | Vedharanyam | MPCA Entry Gate<br>near Ramarpadam   | 2006                              | Entry gate for Small Eco-trial of Medicinal Plants   | The Entry gate is completely damaged   | 1.00                           |
| 4)         | Vedharanyam | Muniappan lake<br>watch tower  | 1920                              | Crucial Watch Tower<br>to observe Animal<br>Movement and doing<br>Anti-Poaching<br>Activities  | The Watch Tower had completely collapsed in Cyclone. Urgent need to build a new one          | 20.00                          |
| 5)         | Vedharanyam | Muniappan lake<br>foot path<br>maintenance   | 1920                              | This foot path leads<br>to the Watch Tower<br>used for Animal<br>movement and Bird<br>Watching | The foot path is completely damaged  | 10.00                          |
| 6)         | Vedharanyam | Forest Guard &<br>Forest Watcher<br>combined<br>quarter at<br>Kodiakadu -2Nos.       | 1969                              | Only Accommodation<br>available to field staff<br>in Vedaranyam                                | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored    | 10.00                          |
| 7)         | Vedharanyam | Kodiakadu<br>Forester<br>Quarters  | 1969                              | No other alternate residence available for staff   | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored    | 10.00                          |
| 8)         | Vedharanyam | Kodiakadu<br>Forester<br>Quarters<br>Campus within<br>Compound Wall                  | 1969                              | No other alternate<br>residence available<br>for staff in<br>Vedaranyam                        | and Syntax Water<br>Storage Tanks have<br>been destroyed.                                    | 20.00                          |
| 9)         | Vedharanyam | Kodiakadu<br>Forest Guard<br>and Forest<br>Watcher<br>Quarters area<br>compound wall | 1969                              | No other alternate residence available for staff   | The Compound wall has broken down. The Gates of the compound wall are damaged beyond repair. | 8.00                           |

| st.<br>No. | Range       | Name of<br>Building   | Year of<br>Const-<br>ruction | Present usage   | Details of damages  | Amount required for renovation |
|------------|-------------|---|------------------------------|---|---|--------------------------------|
| 1          | 2           | 3   | 4                            | 5   | 6   | 7                              |
| 10)        | Vedharanyam | Thainbusainy<br>I Ham (Guest<br>House) Suite- I                       | 1920                         | Heritage Structure<br>built in 1920s. Only<br>Accommodation<br>available for visiting<br>Senior Officers                    | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Ceiling has been completely damaged  | 10.00                          |
| 11)        | Vedharanyam | Thambusamy<br>Illaln (Guest<br>House )Suit-2                          | 1920                         | Heritage Structure<br>built in 1920s. Only<br>Accommodation<br>available for visiting<br>Senior Officers                    | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Ceiling has been completely damaged  | 10.00                          |
| 12)        | Vedharanyam | Tlaarnbusamy Illam (Guest House ) sitting area and landscaping        | 1920                         | Heritage Structure<br>built in 1920s. Only<br>Accommodation<br>available for visiting<br>Senior Officers                    | All the setout areas are completely damaged. Entire Landscaping of the garden outside the rest house is in Ruins  | 20.00                          |
| 13)        | Vedharanyam | Thambusainy Illam<br>(Guest House)<br>driver/staff<br>quarters -2Nos. | 1920                         | No other alternate residence available for staff  | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored   | 10.00                          |
| 14)        | Vedharanyam | Thainbusamy I Ham (Guest House) Equipments and Furniture              | 1920                         | Heritage Structure<br>built in 1920s. Only<br>Accommodation<br>available for visiting<br>Senior Officers                    | Most of the Equipment including Fans, TVs, AC, Bed, Mattress, Dining Table, Cutleryetc have been damaged beyond Repair.                                       | 8.00                           |
| 15)        | Vedharanyam | Blackbuck<br>Guest house -<br>Compound Wall                           | 2000                         | Only accommodation<br>available in Point<br>Calimere for visiting<br>Faculty, Tourists,<br>Study Groups,<br>Researchers etc | The Compound wall<br>of the Guest House<br>has fallen due to tree<br>collapse. Must be<br>restored  | 6.00                           |
| 16)        | Vedharanyam | Blackbuck<br>Guest house -<br>Windows and<br>Doors - 15<br>Rooms      | 2000                         | Only accommodation<br>available in Point<br>Calimere for visiting<br>Faculty, Tourists,<br>Study Groups,<br>Researchers etc | Most of the Windows<br>and Doors of the Rest<br>House have been<br>damaged beyond<br>Repairs. Must be<br>restored   | 10.00                          |
| 17)        | Vedharanyam | Blackbuck<br>Guest house -<br>Bedding and<br>Mattresses - 15<br>Rooms | 2000                         | Only accommodation<br>available in Point<br>Calimere for visiting<br>Faculty, Tourists,<br>Study Groups,<br>Researchers etc | Most of the Beds are<br>broken and Mattresses<br>have water seepages<br>and completely<br>unusable. These are<br>very old and must be<br>replaced immediately | 8.00                           |

| S1.<br>No. | Range       | Name of<br>Building  | Year of<br>Const-<br>ruction | Present usage   | Details of damages   | Amount required for renovation |
|------------|-------------|--|------------------------------|---|--|--------------------------------|
| 1          | 2           | 3  | 4                            | 5   | 6  | 7                              |
| 18)        | Vedharanyam | Blackbuck guest<br>house -<br>Maintenance of<br>Roof, Ceiling,<br>Electrical<br>equipments,<br>Bathrooms etc | 2000                         | Only accommodation<br>available in Point<br>Calimere for visiting<br>Faculty, Tourists,<br>Study Groups,<br>Researchers etc   | Roof, Ceiling, Electrical equipments, Bathrooms etc have partial to complete damage due to cyclone. Overall maintenance of Guest house is absolute necessity | 10.00                          |
| 19)        | Vedharanyam | New flamingo<br>guest House<br>Maintenance - 4<br>Rooms  | 2000                         | Only accommodation<br>available in Point<br>Calimere for visiting<br>Faculty, Tourists,<br>Study Groups,<br>Researchers etc   | Electrical Equipment, Doors, windows, Furniture etc are damaged.   | 8.00                           |
| 20)        | Vedharanyam | Interpretation Centre at Point Calimere Sanctuary  | 2005                         | This interpretation<br>Centre houses various<br>details about the Rich<br>Biodiversity of Point<br>Calimere Sanctuary   | Roof, Infrastructure, Doors, walls, windows etc have been completely damaged   | 4.00                           |
| 21)        | Vedharanyam | MPCA meeting hall maintenance  | 2006                         | This is only conference hall within the Sanctuary which can house 50-60 people for meetings. Visiting Students, Research teams, Visitors use this hall for meetings, presentations, conferences etc | Roof, Infrastructure,<br>Doors, walls, windows<br>etc have been<br>completely damaged  | 10.00                          |
| 22)        | Vedharanyam | Forest Range<br>Officer Quarters<br>maintenance  | 2013                         | Only Accommodation available for FRO, Vedaranyam  | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Ceiling has been completely damaged   | 3.00                           |
| 23)        | Vedharanyam | Maintenance of<br>Foresters<br>Quarters at<br>Kodiakarai   | 1969                         | No other alternate residence available for staff  | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored  | 2.00                           |
| 24)        | Vedharanyam | Maintenance of<br>Forest Guard<br>Quarters at<br>Kodiakarai (2<br>Nos.)                                      | 1969                         | No other alternate<br>residence available<br>for staff  | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored  | 2.00                           |

| SI.<br>No. | Range                        | Name of<br>Building   | Year of<br>Const- | Present usage  | Details of damages  | Amount required for |
|------------|------------------------------|---|-------------------|--|---|---------------------|
| NO.        |                              |   | ruction           |  |   | renovation          |
| 1          | 2                            | 3   | 4                 | 5  | 6   | 7                   |
| 25)        | Nagapattinalr                | Forest Range<br>Officer<br>Quarters,<br>Nagapattinam<br>inaintenance                | 2011              | Only Accommodation available for FRO, Nagapattinam   | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Ceiling has been completely damaged  | 8.00                |
| 26)        | Nagapattinain                | Maintenance of<br>Foresters<br>Quarters at<br>Nagapattinaln                         | 2011              | No other alternate residence available for staff   | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored   | 5.00                |
| 27)        | Sirkhazhi                    | Maintenance of<br>Forest Guard<br>Quarters at<br>Sirkhazhi<br>(2Nos.)               | 2006              | No other alternate residence available for staff   | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored   | 5.00                |
| 28)        | Sirkhazhi                    | Maintenance of<br>Forest Range<br>Office,<br>Sirkhazhi                              | 2006              | FRO, Sirkhazhi<br>Office   | Walls, Roof, Flooring, windows, Doors, Bathrooms are completely damaged. Must be restored   | 5.00                |
| 29)        | Vedharanyam                  | Black buck rest<br>house water<br>facilities  | 2000              | Only accommodation available in Point Calimere for visiting Faculty, Tourists, Study Groups, Researchers etc   | The water pipeline<br>system in the rest<br>house is completely<br>damaged and needs to<br>be replaced  | 2.00                |
| 30)        | Vedharanyam                  | Over Head Tank<br>in Adhivasi<br>colony for<br>Water Supply<br>during Dry<br>season | 2011              | Water is pumped into<br>the Water Troughs of<br>Sanctuary using this<br>Over Head Tank<br>during Dry Seasons.<br>Highly essential Tank<br>for water Supply in<br>Summers | The existing OHT is already in unstable condition before cyclone. The tank is completely unusable for water storage and pumping after the cyclone due to severe damage to the structure | 25.00               |
| 31)        | Vedharanyam                  | Maintenance of sanctuary area compound wall   | 2011              | Compound Wall is<br>the demarcation<br>between the<br>Sanctuary and outside<br>area  | The compound wall suffered damages at various parts   | 20.00               |
| 32)        | Vedharanyam<br>Nagapattinain | Sanctuary area<br>Signage and<br>information<br>board (75<br>boards)                | 2011              | Signage and Information boards are necessary for the visitor's information and promotion of the Sanctuary  | 90% of the Signages<br>and Information<br>boards have collapsed<br>due to very high<br>intensity winds  | 20.00               |

| Sl.<br>No. | Range       | Name of<br>Building   | Year of<br>Const-<br>ruction | Present usage   | Details of damages  | Amount required for renovation |
|------------|-------------|---|------------------------------|---|---|--------------------------------|
| 1          | 2           | 3   | 4                            | 5   | 6   | 7                              |
| 33)        | Vedharanyam | No.3 Gate ticket counter maintenance  | 2012                         | For Visiting Public with small information boards   | Doors, Windows,<br>Computer, Furniture<br>etc has been damaged  | 5.00                           |
| 34)        | Vedharanyam | Near No.3 gate incomplete building (antipoaching house) construction  | 2012                         | Highly essential for<br>the stationed staff in<br>the Sanctuary   | The building was left<br>incomplete due to lack<br>of funding and parts of<br>it is damaged in the<br>cyclone | 20.00                          |
| 35)        | Vedharanyam | Maintenance of interpretation centre at No.3 gate   | 2005                         | This interpretation<br>Centre houses various<br>details about the Rich<br>Biodiversity of Point<br>Calimere Sanctuary   | Doors, windows, furniture etc damaged   | 2.00                           |
| 36)        | Vedharanyam | Maintenance of<br>Eco shop centre<br>at No.3 gate   | 2005                         | Eco-Shop to sell<br>Souvenirs and other<br>items  | Doors, windows, furniture etc damaged   | 1.00                           |
| 37)        | Vedharanyam | Maintenance of entrance arch at sanctuary   | 2003                         | Entrance Arch   | Damages and<br>Maintenance<br>works   | 1.00                           |
| 38)        | Vedharanyam | Maintenance of sanctuary road   | 2003                         | This is the only motorable earthem  | 1. Desilting of side drain  | 2.00                           |
|            |             | from No.3 Gate  |                              | road as of now within   | 2. filling of pot holes   | 20.00                          |
|            |             | to Chozha light house   |                              | the sanctuary for<br>Eco-Tourism and<br>Anti-Poaching   | 3. Cause ways and<br>Irish bridges repair<br>works  | 20.00                          |
|            |             |   |                              | Activities. The road is also used to provide water to wildlife through tankers during dry seasons   | 4. Side wall repair works   | 6.00                           |
| 39)        | Vedharanyam | Old chozha light house maintenance  | 2003                         | Heritage structure<br>and landmark of<br>Sanctuary  | Damages and<br>Maintenance works  | 3.00                           |
| 40)        | Vedharanyam | Maintenance of<br>beach watch<br>tower  | 2006                         | Crucial Watch Tower<br>to observe Animal<br>Movement and doing<br>Anti-Poaching<br>Activities   | Damages and<br>Maintenance<br>works   | 1.00                           |
| 41)        | Vedharanyam | Maintenance of managed watch tower  | 2006                         | Crucial Watch Tower<br>to observe Animal<br>Movement and doing<br>Anti-Poaching<br>Activities   | Damages and<br>Maintenance<br>works   | 3.00                           |
| 42)        | Vedharanyam | Tobacco well near<br>Adhivasi colony<br>maintenance -<br>motor, motor shed<br>and compound<br>wall repair etc | 2011                         | Water is pumped into<br>the Water Troughs ot"<br>Sanctuary from these<br>wells during Dry<br>Seasons. Highly<br>essential Tank for water<br>Supply in Summers | Pipeline system, Motor shed, Motors, well system etc have been completed damaged                              | 20.00                          |

| st. | Range                                    | Name of   | Year of<br>Const- | Present usage   | Details of damages  | Amount required for |
|-----|--|---|-------------------|---|---|---------------------|
| No. | Runge                                    | Building  | ruction           | Tresent usage   | Details of damages  | renovation          |
| 1   | 2  | 3   | 4                 | 5   | 6   | 7                   |
| 43) | Vedharanyam                              | MGR Nagar<br>committee hall<br>maintenance                              | 2011              | Meeting hall for<br>conducting EDC<br>Meetings              | Roof, Doors,<br>Windows etc<br>Damaged  | 1.50                |
| 44) | Vedharanyam                              | Mettu street<br>committee hall<br>maintenance                           | 2011              | Meeting hall for conducting EDC Meetings                    | Roof, Doors,<br>Windows etc<br>Damaged  | 2.00                |
| 45) | Vedharanyam                              | Anna Nagar<br>committee hall<br>maintenance                             | 2011              | Meeting hall for<br>conducting EDC<br>Meetings              | Roof, Doors,<br>Windows etc<br>Damaged  | 1.50                |
| 46) | Vedharanyam<br>Nagapattinam<br>Sirkhazhi | Olive Ridley<br>Turtle egg<br>hatching centre<br>(8 Nos.)               | 2011              | Temporary hatchery for olive ridley conservation            | Temporary hatcheries have been completely wiped off during cyclone  | 4.00                |
| 47) | Vedharanyam                              | Maintenance of library hall at Aarkattuthurai                           | 2011              | Meeting hall for conducting EDC Meetings                    | Roof, Doors,<br>Windows Damaged   | 1.00                |
| 48) | Vedharanyam                              | Maintenance of committee hall at Kovilthavu                             | 2011              | Meeting hall for conducting EDC Meetings                    | Roof, Doors,<br>Windows Damaged   | 2.00                |
| 49) | Vedharanyam                              | Vehicle<br>maintenance<br>EDMC, SML<br>van                              |                   | Used for Eco-<br>Tourism Purpose                            | Vehicle damaged   | 0.75                |
| 50) | Vedharanyam                              | Vehicle<br>maintenance of<br>EDC van                                    |                   | Used for Eco-<br>Tourism Purpose                            | Vehicle damaged   | 1.00                |
| 51) | Vedharanyam                              | Maintenance<br>committee hall<br>(FDA) at<br>Kodiakadu                  | 1969              | Meeting hall for conducting EDC Meetings                    | Roof, Doors,<br>Windows Damaged   | 4.00                |
| 52) | Vedharanyam                              | Camera tap (10 Nos.)  |                   | No camera traps<br>available as of now<br>with the division | Essential for tracking the animal movement  | 5.00                |
| 53) | Vedharanyam                              | Solar panel,<br>inverter and<br>battery for<br>black buck rest<br>house |                   | No inventor, battery etc are available as of now            | Essential for the guest house   | 5.00                |
| 54) | Vedharanyam                              | Generator for blackbuck rest house                                      | 2000              | No Generator<br>available for rest<br>house as of now       | Essential for the guest house   | 3.00                |
| 55) | Nagapattinam                             | Maintenance of<br>Wildlife<br>Warden Office                             | 2013              | Wildlife Warden<br>Office                                   | Gates, Windows, Doors, Outside Garden Area etchave been damaged partially to fully. Furniture also was damaged. | 5.00                |

| SI.<br>No. | Range                                    | Name of<br>Building                                       | Year of<br>Const-<br>ruction | Present usage   | Details of damages   | Amount required for renovation |
|------------|--|---|------------------------------|---|--|--------------------------------|
| 1          | 2  | 3   | 4                            | 5   | 6  | 7                              |
| 56)        | Nagapattinam                             | Maintenance of<br>Wildlife<br>Warden Camp<br>Office       | 2013                         | Wildlife Warden<br>Camp Office                        | Gates, Windows, Doors, Outside Garden Area etc have been damaged partially to fully. Furniture also was damaged. | 8.00                           |
| 57)        | Nagapattinam                             | Maintenance of<br>Forest Range<br>office,<br>Nagapattinam | 2013                         | FRO, Nagapattinam<br>Office                           | Gates, Windows, Doors, Outside Garden Areaetchave been damaged partially to fully. Furniture also was damaged.   | 5.00                           |
| 58)        | Sirkhazhi                                | Maintenance of<br>Forest Range<br>office, Sirkhazhi       | 2013                         | FRO, Sirkhazhi<br>Office                              | Gates, Windows, Doors, Outside Garden Area etc have been damaged partially to fully. Furniture also was damaged. | 5.00                           |
| 59)        | Vedharanyam<br>Nagapattinam<br>Sirkhazhi | Generators for<br>Range offices<br>and WLW<br>office      |                              | No Generator<br>available for rest<br>house as of now | Essential for the guest house  | 3.00                           |
| 60)        | Vedharanyam<br>Nagapattinam<br>Sirkhazhi | Clearing<br>Works of<br>Debris                            |                              | Debris in various<br>Places                           | Clearing debris is immediate requirements  | 5.00                           |
|            |  |   | Total C                      | Cost  |  | 465.75                         |

for Principal Chief Conservator of Forests & Chief Wildlife Warden