

GOVERNMENT OF INDIA
MINISTRY OF COAL

RAJYA SABHA
STARRED QUESTION NO. 99
ANSWERED ON- 09.02.2026

ACCIDENTS IN COAL MINES

*99 SHRI SANDOSH KUMAR P:

Will the Minister of COAL be pleased to state:

- (a) the number of accidents in coal mines in the country during 2022-25 and the total number of deaths caused by accidents during this period;
- (b) the reasons for each accidents and the corrective measures taken after the accidents;
- (c) whether the victims were provided compensations, if any; and
- (d) if so, the details thereof?

ANSWER

MINISTER OF COAL & MINES
(SHRI G. KISHAN REDDY)

(a) to (d): A statement is laid on the Table of the House.

STATEMENT REFERRED TO IN REPLY TO PARTS (a) TO (d) OF THE RAJYA SABHA STARRED QUESTION NO. 99 TO BE ANSWERED ON 09.02.2026 ASKED BY SHRI SANDOSH KUMAR P, HON'BLE MP REGARDING 'ACCIDENTS IN COAL MINES'.

(a): The number of accidents in coal mines in the country during the period 2022-25 and the total number of deaths caused by such accidents are as follows:-

Year	Number of Fatal Accidents	Fatalities	Number of Serious Accidents
2022	24	28	181
2023	38	41	117
2024	38	49	119
2025*	44	54	118

*Data of year 2025 is provisional.

(b): The causes of each fatal/ serious accident, year-wise, are attached at Annexure-I.

The following corrective measures have been taken to prevent the occurrence of such accidents:-

1. Introduction of Root Cause Analysis (RCA) based Accident Investigations mechanism.
2. Formulation and implementation of Hazard Identification and Risk Assessment (HIRA) based Safety Management Plans (SMPs), Standard Operating Procedures (SOPs), Code of Practices (COPs) and Scientific Study-based Strata Control and Monitoring Plans (SCAMPs)
3. Mine Safety Audit
4. Safety Awareness Programs: Video clips and animation films focusing on safety.
5. Open Cast Mine Safety Measures:
 - a. Roll out of blast-free mining with eco-friendly surface miners
 - b. Formulation and implementation of mine-specific Transport Rules
 - c. Simulator-based training for HEMM operators
 - d. Competency Assessment for HEMM Operators through Competency Board
 - e. Dumpers and other HEMM with advanced safety features
6. Development of National Coal Mine Safety Reporting Portal (NCMR) and Centralised Safety Information System (CSIS) for consolidated data collection, analysis, and monitoring.

(c) & (d): Yes, the compensation is provided to the family in case of injuries and deaths by the respective coal companies as per the provisions of the Employees' Compensation Act, 1923 which, inter-alia, provides for payment of compensation to employees and their dependents in case of injury and accident arising out of and in the course of employment and resulting in disablement or death. The Act is implemented by the State/ Union Territories.

Coal India Limited provides statutory compensation under the Employees' Compensation Act, 1923, and a special relief/ ex-gratia payment of ₹25 lakhs. In addition, the family of a deceased departmental employee is entitled to ₹1,56,250 under the Life Cover Scheme (LCS) and an ex-gratia amount of ₹90,000 as per National Coal Wage Agreement (NCWA-XI). Employment is also provided to an eligible dependent of the deceased departmental employee or monetary compensation in case of refusal of employment. Further, insurance coverage under the Corporate Salary Package Account is provided @ ₹1 crore for departmental employees and @ ₹40 lakhs for contractual employees.

Annexure-I

ANNEXURE REFERRED TO IN REPLY TO PART (b) OF RAJYA SABHA STARRED QUESTION NO. 99 FOR 09.02.2026 BY SHRI SANDOSH KUMAR P, REGARDING ACCIDENTS IN COAL MINES.

The cause for each accident, year-wise, during 2022-25:

Sl. No.	Date of Accident	Name of the Mine	No. of Fatality	Cause of accident
1	02-01-2025	Kakatiyakhani Opencast-III Project	1	While an empty tipper was on its way towards overburden face of an opencast coal mine, it hit the rear end of stationary tipper waiting at a three way junction causing serious bodily injuries to the empty tipper driver, which turned into fatal after six days while treatment in a hospital.”
2	03-01-2025	Khottadih Colliery	1	While a person approached the edge of a strata bunker of an underground coal mine, he fell into the bunker, which was 52 meters deep, sustaining serious bodily and succumbed on the spot.
3	05-01-2025	Kankanee Colliery	1	While an excavator of boom height 7m was loading coal from the toe of a 29m high bench of a fiery opencast coal mine, a large quantity of hot fiery strata slid from the sides of high bench causing breakage of window glass pane of the excavator and some portion of hot strata fell into pool of water which was being used to extinguish burning coal resulting formation of steam which entered inside the operator’s cabin inflicting serious burn injury to the excavator operator to which he succumbed after a period of one day in the hospital.
4	09-01-2025	Basantimata Dahibari	1	While a 60 tonne dumper was clumping overburden in an opencast coal mine, some boulders fell on the body of a person standing on the rear side of the dumper inflicting him serious bodily

				injuries which turned into fatal on the spot.
5	04-02-2025	Jhanjra Project Colliery	1	While a fitter was examining the snub drum of a running belt conveyor installed at drive head unit in a belowground coal mine, his left hand was entangled between snub drum and belt conveyor causing severing of his left hand from shoulder which turned into fatal at the spot”.
6	12-02-2025	Kujama OCP	1	While an Electrician was pulling a 185Sq.mm XLPE cable towards a 11KV vacuum Circuit Breaker in the surface Sub-station of an open cast coal mine, suddenly he slipped and inadvertently came in contact with the live 11KV busbar of above mentioned switchgear, received electric shock and burn injuries to which he succumbed on the way to hospital”.
7	20-02-2025	NCPH Colliery R-6 Mine	1	While LHD operator, operating his LHD in a gallery to reach to face for lifting of blasted coal from the face, front portion roof bolt, loosely affixed in w- strap in the roof for reducing the sagging in electric trailing cable of UDM Machine crossing across the gallery in the roof tied with installed roof bolts, pierced/penetrated in his neck below left ear to which he succumbed to his injury while shifting to the Hospital"
8	06-03-2025	Chhattarpur Mine-1	3	While three persons entered under a freshly exposed unsupported roof in development face of a belowground coal mine, suddenly a layer of sandstone roof measuring about 6.36m in length, 5.5m in width and 0.2m to 0.3m in thickness, dislodged from a height of 2.5m and fell over them

				inflicting grievous injuries to which all three of them succumbed instantly.”
9	12-03-2025	Balram(Kalinga) OCP	1	While four(4) workers, standing on trestles(TR14, TR15) trying to align a pre-fabricated structure (conveyor gallery) of about 11T weight on the two trestles (TR14, TR15) i.e., matching of holes of the conveyor gallery with the holes of trestles with help of Crane in the process of alignment, two slings out of four slings tied with conveyor gallery came out from the hook of the crane, the conveyor gallery slide down and hit the trestle (TR 15) towards the SILO side, fell down on the floor along with trestle(TR15), injuring one worker fatally, one co-worker escaped with minor injury and remaining two co-workers standing on trestle(TR14) escaped unhurt.”
10	19-03-2025	Karma Open cast Project	1	While a water tanker was going into the mine, stopped suddenly due to engine block burst and subsequently it rolled down the gradient and hit the highwall side and toppled on the haul road causing serious injury to the operator, whose health condition worsened due to prevailing health issues and post-surgery complications, to which he succumbed after ten days while at the hospital.”
11	21-03-2025	AMLOHRI OCP	1	While a workman was greasing the shovel bucket at overburden bench of an opencast coal mine, the service van for greasing, while being reversed towards the shovel bucket pressed the workmen between the rear portion of the service van and the shovel bucket inflicting serious injuries, to which he succumbed while being treated at hospital”.

12	18-04-2025	Gare Palma IV/2 & 32 Opencast Coal Mine	32	While a group of three persons, sitting inside the truck mounted blasting shelter, kept at 165m from the blasting site, were conducting deep hole blasting in an opencast coal mine, a blasting projectile measuring about 0.3m x 0.25m x 0.21m hit and penetrated the blasting shelter inflicting fatal injuries to one of them on the spot, one person succumbed to his injuries after two days while undergoing treatment and rest one person was seriously injured.”
13	22-04-2025	Churcha Mine (RO)	1	While a person was engaged for handling of trailing cable of stuck Twin Bolter which was being pulled by a battery hauler by use of a steel chain, in an underground coal mine, suddenly the Twin Bolter got released from Jam and hit the worker on his abdomen, causing serious bodily injuries, to which he succumbed about 02 hrs later.
14	27-04-2025	DULANGA COAL MINING PROJECT	1	While a minibus was transporting workmen from a parking yard to the Attendance Room at the end of their shift in an opencast coal mine, it's driver momentarily lost his attentiveness and control, causing the bus to overturn to left side as its right-side tyres climbed onto the road divider, during which one of the workmen riding therein got thrown out of its door and caught between the hard road surface and body of the toppled bus, receiving serious bodily injuries and was subsequently declared brought dead on being shifted to hospital.
15	Accident Occurred on 16-02-2025 Turned Into Fatal on 04-05-2025	Ramnagore Colliery	1	While a dumper loaded with overburden material was heading towards internal dump in an opencast coal mine, the dumper swayed on its left side, moved over overburden heap lying outside the haul road and tilted on its right resulting in serious bodily

				injuries to the dumper operator which turned into fatal after 77 days during his treatment in the hospital.
16	05-05-2025	GODAVARIKHANI COAL MINE (No.2&2A and No.5)	1	“While a person was driving the water tanker on a haul road of an opencast coal mine, suddenly he lost control, fell down on the ground and was run over by right rear tyre of the same water tanker, resulted in to crushed head injury to which he succumbed instantaneously”.
17	10-05-2025	Bharatpur OCP	1	While a contractual worker deputed to supervise coal-transportation was standing at a slightly elevated place about 50m away from a coal face in an opencast mine, a pay loader being reversed for parking at the end of 3rd shift hit him, when in an attempt to save himself, he jumped and fell on boulders lying nearby, in which he sustained internal injuries, lost consciousness and later declared brought dead on being taken to hospital."
18	12-05-2025	Giddi A OCP	1	“While a 60 Tonne dumper was being positioned near a shovel for taking load at an overburden face of an opencast coal mine, an overman, who was present in the vicinity for supervision, was run over by front left wheel of the dumper receiving serious bodily injuries and later declared brought dead on being taken to hospital.”
19	18-06-2025	Gevra OC Mine	1	“While a person was engaged in maintenance work on 6.6 kV power cable joints at Coal Handling Plant in an Opencast Coal Mine, he inadvertently came in contact with energized 6.6 kV power cable temporary joint of an adjacent belt conveyor, received an electric shock, to which he succumbed on the way to hospital.”

20	19-06-2025	Parej East Open Cast Project	1	While an electric shovel was doing face preparation for loading of coal at a coal bench of an opencast mine, the shovel operator, perplexed by the noise of a side fall from another nearby bench at about 30 m away, suddenly swung the shovel, in which an overman present nearby for supervision was hit by bucket of the shovel, receiving serious head injuries, to which he succumbed to his injuries on the way to the hospital"
21	29-06-2025	Kedla Underground Project	1	While an Electric Helper and a General Mazdoor were working on a pole in the 11 KV overhead line by positioning themselves at a height of 6.5 Meters without safety belt and 8 Meters with safety belt respectively and without following proper shutdown procedures, they got electrocuted, which resulted in fall of the Electric Helper from the height of 6.5 Meters leading to fatal injuries and the General Mazdoor received serious burn injuries.”
22	10-07-2025	AMALGAMATED SENDRA BANSJORA NICHITPUR COLLIERY	1	While a dumper was negotiating a blind right turn on a haul road of an open cast coal mine, it collided with another stationary dumper and, in that course, hit a person inflicting him serious bodily injuries in which he succumbed instantaneously.
23	23-07-2025	Gevra OC Mine	1	While a drill helper was crossing a haul road, near an overburden face of an opencast coal mine, suddenly he was hit by an empty truck and received serious bodily injuries to which he succumbed subsequently.
24	27-07-2025	NCPH Colliery R-6 Mine	1	While a crew was engaged in replacing surface conveyor belt of an underground coal mine, the belt was being pulled by inch starting of motor from the tail end and a workman (tyndal) was manually positioning the

				belt near the drive drum (out of sight from tail end), suddenly he got pulled by the moving conveyor and entrapped between the belt & drive drum causing mutilation of body parts to which he succumbed instantly on the spot.”
25	01-08-2025	KALYANKHANI INCLINE MINE	-51	While a person was trying to board into the operator cabin of a Side Discharge Loader (SDL) after cleaning the blasted coal pieces stuck beneath the SDL’s rear end frame at the corner of a slice of the depillaring panel in a below ground coal mine, suddenly a piece of shaly coal measuring about 1.1 m (length) x 0.25 m (width) x 0.25 m (thick) parted from the side of the rib and fell over him resulted into serious bodily injury to which he succumbed on the way to hospital
26	20-08-2025	Gare Palma IV/7 coal mine	1	On date 20/08/2025 around 5.45 am an incident occurred at parking area of Gare Palma IV/7 Coal Mine within the mine leasehold area. Outside dispatch truck driver Shri Vijay Kumar Kol, (Age - 38 yrs) of M/s Shri Nivas Road lines Transport, Raipur was found dead condition near his truck number CG-04 NV 6898 at parking area of the mine.
27	20-08-2025	Shyamsundarpur Colliery	1	While a gallery was being developed by Continuous Miner in a belowground coal mine, it got connected with an old waterlogged working situated in the same seam, causing inrush of water resulting in drowning of Continuous Miner operator due to which he succumbed on the spot.”
28	05-09-2025	Amalgamted Keshalpur West Mudidih	7	While a service van carrying six persons including driver were travelling on the haul road of an opencast coal mine, a part of highwall strata measuring size of about 50m (length) X 24m (width) X 10m (height) situated immediately above the haul

				road collapsed, pushed the vehicle off the road into water accumulated 70m below the haul road resulting fatal injuries to all six persons on the spot and an outsider present in the vicinity also received fatal injury.
29	08-09-2025	INTEGRATED LAKHANPUR BELPAHAR LILARI OCP	1	While a contractual security guard was washing his hands at a small pool of water near a water tanker's filling point at an opencast coal mine, a truck which was being reversed just after it's windshield cleaned hit him, causing him to fall backward and receiving serious head injuries due to hitting on the concrete floor, to which he succumbed on the way to hospital."
30	24-09-2025	Urimari Open cast Project	1	While two workers, including a female worker, were engaged in stemming of a shot hole charged with explosives in an opencast coal mine, suddenly, the shot hole exploded pre-maturely due to hotness inside the hole, as a result of which both the workers sustained severe injuries, one of them succumbed to his injuries while being transported to the hospital, and the other female co-worker survived with serious bodily injuries."
31	02-10-2025	Ballarpur 3&4 Pits	1	At around 12:25 AM midnight, Shri. Hemraj Bhaurao Dhawas, Pump Khalasi, was going down by 4 No. cage. When the cage had descended to about 25-30 meters from the surface, the Banksman heard a shouting sound from the shaft. The Banksman immediately stopped and signalled to raise the cage. On checking, it was found that the person (Shri. Hemraj Bhaurao Dhawas) was not present in the cage. The Onsetter at the shaft bottom confirmed that the person had jumped from the descending cage, maybe an act of suicide. He was subsequently found dead at pit bottom

32	08-10-2025	Nigahi OCP	1	At about 02:20 AM on 08.10.2025 (third shift of 07.10.2025), a coal-loaded tipper (Reg. No. UP64CT4158) of M/s Maihar Cement and Pipe Industries Ltd. while tipper moving on the left side of the road between surface miner and weighbridge it crossed road diagonally breaches the berm and then toppled and fell down to a lower bench while moving from the Surface Miner Bench (East Section) to Morwa Siding (SPUR-2) on the coal transport road. The driver, Shri Tarkeshwar Patel, sustained serious injuries and was shifted to NSC, Jayant, where he was declared dead by the attending doctor.
33	09-10-2025	Gevra OC Mine	1	At Gevra project on dated 09/10/2025 in 2nd shift, at about 6.10 PM, one coal loaded trailer No- CG 12 AS 0812 belonging to M/S-Aryan Coal Beneficiation after taking load from Old Dipka stock, the driver was going for final weighment at weigh bridge No- 10 but crossed the berm near tri-junction behind west MTK. It seems that the driver of the trailer namely Shri Sanup Tigga, aged about 34 Years lost control over the trailer and hit the berm of the road. The driver might have jumped from the trailer causing severe injury in head. He was sent to NCH Gevra, where he was declared dead.
34	09-10-2025	Amalgamated Inder-Kamptee Deep OC Mine	1	On date 09.10.2025, Shri Shrikant Ramkrushna Nitnaware was deployed as Shovel Operator on excavator no. 179 in 2nd shift in Departmental Kamptee patch of the mine. At around 8.30 pm, Shri Raviprakash, Mining Sirdar observed that excavator no. 179 was marching in unplanned/uncontrolled manner & the excavator had stopped away from loading point. Further dumper loading was also stopped. When mining sirdar came close to excavator, he noticed,

				that the excavator operator, Shri Shrikant Nitnaware was not present in the excavator. Then he saw crushed body of Shri Shrikant Nitnaware on the path that excavator had travelled just now. The Operator Shri Shrikant was run over by his own machine and on the basis of the circumstantial evidences, prima facie it appears to be a case of suicide.
35	11-10-2025	Amlai Opencast Mine	1	Blasted OB was being dumped at Magazine patch bottom dump over existing old pump station platform/bench for levelling and strengthening purpose. At about 05:00 PM due to failure of lower deck of the platform where dumping was being carried out, sudden dump slid down/shearing occurred. In this incident, one dozer and one tipper of M/s-RKTC Infratech slid down into the accumulated water. Dozer operator Shri Chandan Kushwaha, who also got involved in this incident, were immediately rescued and sent to Burhar Central Hospital Dhanpuri for treatment but tipper along with operator Shri Anil Kushwaha went drowned and dozer operator Shri Chandan Kushwaha suffered fracture in left hand one metacarpal and searching operation is still being carried out.
36	18-10-2025	Tara (East & West) Coal Mine	1	While a tipper was moving on haul road in reverse direction to load overburden in an opencast coal mine, an unqualified supervisor walking on the haul road was run over by the tipper, sustained serious bodily injuries and was declared brought dead in the hospital.
37	24-10-2025	Duchichua OCP	1	On dated 24.10.2025 at about 11.00 pm in IIIrd shift (Night Shift), Pushendra Singh S/o Shri Banke Lal

				Singh aged about 50 years(DOB-12.12.1975), Designation – Mazdoor of M/s GSCO Infrastructure Pvt. Ltd.(an outsourced HOE company) was inadvertently hit by the dozer of the same HOE agency at the dumping in East OB dump of the Dudhichua mine and was fatally injured .
38	26-10-2025	Gopalichuck Colliery	1	A boulder suddenly rolled from the south-west highwall of the mine and struck the diesel tanker, causing it to topple. As a result, three person in the diesel tanker received injuries.
39	04-11-2025	KDH Opencast Project	1	At approx 8pm on 04.11.2025 ,Mr Sukhdev Ganjhu who was working at the bunker construction site under M/s Madhucon Projects Ltd.,KDH Project,NK Area was coming down after completing his job slipped from the stairs and fell down resulting in serious head injury and was sent to Dakra Central Hospital for initial treatment at Mahavir Manipal Hospital, Ranchi he was declared dead in emergency ward at around 10:56pm on 04.11.2025.
40	17-11-2025	Dudhichua OCP	1	On 17/11/2025, at around 1:30 PM, at Dudhichua CHP Crusher No. 3, Sri Ram Sajiwan Vaish, Fitter, EIS No. 26118489 (Departmental), aged 52 years was allegedly hit on forehead standing nearby, by arm of breakdown rock breaker. Clearing work of jammed crusher was going on by Back Hoe, meanwhile, the boom of Back Hoe collided with boom of breakdown rock breaker. Consequently, Rock breaker arm moved and allegedly hit on forehead of the victim standing nearby. He was immediately rushed to NSC, hospital where he was declared brought dead.

41	23-11-2025	Jharkhand Project	Opencast	1	On 23.11.2025 during the General Shift, a departmental truck with driver were engaged for loading of pump at workshop area. The truck parked at the site for loading started moving unexpectedly in forward direction and the driver tried to climb the running truck , fell on the ground causing serious injury. He was shifted to nearby hospital where it was advised after first aid to shift to other hospital for better treatment and the injured succumbed on the way.
42	30-11-2025	Jayant OCP		1	While fitting rollers onto the roller frame of Belt No. 1. at approximately 11:30 AM, Shri. Arvind Khairwar, Contractual helper fainted and was taken to the hospital, where he was declared died. The reason of death is being enquired. Apart from other reasons, the possibility of electrocution is also being examined. Final reason will be confirmed by post mortem report.
43	20-12-2025	Urimari Open cast Project		2	A Fatal accident occurred at Contractual Patch of Urimari OCP, Barka-Sayal Area of M/s Central Coalfields Limited, on 20th December 2025 at about 21:45 hours (end of 2nd shift) in which two persons, namely- 1. Sri Sunil Yadav, Tipper Driver, age about 29 years 2. Sri Raju Paswan, Dump-man, age about 55 years, were fatally injured due to partial bench slide on the tipper stationed for loading at toe of the lower bench. Probable Cause of accident as reported partial OB bench slide probably due to some hidden fault/ folds. Detailed enquiry is under process to ascertain the exact cause and contributing factors

44	25-12-2025	Amalgamated Amlo Dhori Opencast Mine	1	At around 11:30 am on dated 25.12.2025, Himanshu Raj, ITI Fitter, contractor's employee of M/s Minsol Limited under AADOCM, Dhori Area, CCL who was deployed at pumping station of Highwall Patch for supervision and maintenance of pumping and dewatering, he slipped down near pumping station during his supervision and got head injury. He was immediately taken to the Central Hospital Dhori for treatment. After diagnosis, he has been referred to KM Memorial Hospital, Bokaro for specialized treatment. The KM Memorial Hospital, Bokaro after preliminary investigation declared him dead.
45	08-01-2024	Kasipet 2 Incline	1	While a person was proceeding to drinking water point in congested haulage roadway of a development belowground coal mine, suddenly he got skidded on trackline and fell down and hit the derailed tub existed adjacent to haulage trackline, resulted into serious bodily injury to his right leg (with fracture) and succumbed in the hospital after 17 days during medical treatment.
46	22/01/2024 T/T/F/ 28/01/2024	Godavrikhani Coal Mine [No. 2 & 2A and No. 5]	1	“While a set of five empty tubs were being hauled by a direct rope haulage in a de-pillaring district of a belowground coal mine, tub attached with the rope got derailed, suddenly the second tub separated from the first tub and the set of four empty tubs were ran back for a distance of about 70 m and hit Sirdar, who was at the junction of endless haulage, along with trammer and other two persons, inflicting serious bodily injuries to Sirdar & others were escaped unhurt, and Sirdar succumbed to his injuries in the hospital after seven days”.

47	29-01-2024	Krishnashila OCP	1	While the contractor operator of an empty tipper, parked his tipper near the PC which was under maintenance by two contractual workers in the OB bench of an opencast coal mine, alighted his cabin with the engine in 'ON' position, suddenly the tipper rolled back on its own in uncontrolled manner, which ran over one of the worker, inflicting him serious bodily injuries to which he succumbed almost instantaneously".
48	17-02-2024	Kusmunda OC Mine	1	While a contractual worker was removing a detached roller and broken liner pieces from beneath the moving belt conveyor in an opencast coal mine, his band got entrapped in between roller and conveyor belt and was severely pulled, causing him serious internal bodily injuries to which he succumbed while being treated at hospital.
49	19-02-2024	Kurja UG Colliery	1	While a Battery Hauler Machine Operator after parking the Battery Hauler entered into the route of another Battery Hauler in an underground coal mine, he was hit by the Battery Hauler going to unload the coal on feeder breaker on that route, inflicting serious bodily injuries to which he succumbed during treatment at the hospital after about twenty-four hours.
50	06-03-2024	Churcha Mine (RO)	1	While a worker was present in continuous miner depillaring panel and was standing in NO GO ZONE, i.e. at the corner of split Junction of pillar under extraction and CM machine was loading the RAM CAR by sweeping & cleaning the split gallery before start of slicing, suddenly a violent coal bump occurred in pillar under extraction and lumps of coal parted from the unsupported side wall, out of fear he run away hurriedly and fell on to the

				ground, inflicting serious bodily injury to head, legs and forearm injuries, he was referred to super specialty hospital after primary treatment at the regional hospital of the mine, where he was declared brought dead.”
51	16-03-2024	KalyanKhani No. 1 Incline Mine	1	While a bunch of W - straps weighing about 1.25 tons was being lifted using a nylon round sling by a mobile crane in a store yard, the impaired sling snapped near the crane hook and the bunch of W-straps fell on a person from a height of about 1.5m, who was assisting the rigging loads, due to which he sustained serious bodily injuries and succumbed on the way to hospital.
52	02-04-2024	Chinakuri Mine No 1	2	While a crew of five contract workers engaged in repair work of headgear structure were cleaning the bell plate platform sheets located at height of twenty meters, the bell plate platform along with guide rope clamp mounting girder failed from one side resulting in fall of two persons. One of them fell into the shaft bottom along with safety belt and received fatal injury while other hanged with safety belt but was inflicted serious bodily injury due to platform and rope to which he scummed after a few minutes.
53	10-04-2024	Urtan North U/G Coal Mine	1	While a person from top of box cut was observing the status of dewatering operation being carried out at the bottom of box cut excavated for an underground coal mine, fell down from a height of about 11.5m and also a stone boulder measuring 1.0m x 0.75m x 0.60m size dislodged from about 2.5m height fell on him causing serious bodily injury to which he succumbed during treatment at the hospital”

54	23-04-2024	Nigahi OCP	1	While a hired light motor vehicle driven by contractor's driver with 05 employees was passing from front right corner of a stationary Dumper waiting in queue on the haul road for taking load in an opencast coal mine, it suddenly moved forward and run over the light motor vehicle by front and then rear right side wheels, inflicting serious bodily injuries to 04 persons of which one person succumbed to injuries during treatment in hospital after one and half hour when other two escaped with minor injuries".
55	24-04-2024	Integrated Lakhanpur Belpahar Lilari OCP	1	"While truck driver was exiting in hurry with loaded truck from coal stock yard, on the haul road having nearly 1 in 90 gradient and 13 m to 18 m wide, a security guard whilst talking over mobile phone at his non-designated work place, inadvertently entered in close proximity of running truck was hit and partially run-over by its front right side wheel received serious bodily injuries, to which he succumbed on the way to hospital"
56	10-05-2024	Parasea Colliery	1	While, a trammer was coming out from the cage pushing an empty coal tub at the pit-bottom of a belowground coal mine, stone pieces having size 37 cm X 15 cm X 15 cm, 25 cm X 10cm X 10cm fallen from sides of shaft over protective roofing and cage canopy, got broken into pieces and hit on the head and back of neck of the trammer inflicting serious bodily injurie to him, due to which he succumbed instantly.
57	10-05-2024	Amod(G-19 Extn.) Lignite mine	1	"While an excavator operator was cutting a drain at the bottom overburden bench, of an opencast lignite mine, suddenly the in-pit overburden dump, back filled against an in-situ barrier of overburden benches, slid down, burying the

				excavator along with its operator, resulting into fatality of the operator instantly”.
58	12-05-2024	Kabribad Mine Reorganised	1	“While a person was performing maintenance work on a Dozer on an overburden dump, he accidentally drove off on it and the Dozer slid down along the slope of the dump to a depth of about 25 m during which he received grievous bodily injuries and succumbed to the injuries while undergoing treatment in a hospital.”
59	15-05-2025	JAMBAD COLLIERY	1	While a trammer was approaching to pull the empty tubs from the winder cage at Pit bottom in a belowground coal mine, a spring of temporary Pit bottom buffer was detached from mounting girder and carried away by the ascending winding cage bottom channel and fell down from 151 meters height and bounced back thereby hitting the victim in his forehead causing serious injury to which he succumbed almost instantaneously”.
60	22-05-2024	Dudhichua OCP	2	While a contractual welder and helper were engaged for repairing and installation of firefighting water hydrant line over bottom deck plate of a belt conveyor of coal handling plant of an opencast coal mine, suddenly the support angle of the deck plate dislodged to which they both fell down from a height of about 17 m on concrete floor and received serious bodily injury to which they succumbed almost instantaneously on the spot”.
61	24-05-2024	Sasti Expansion Opencast Mine	1	While a security guard deployed for guarding the machinery in an internal overburden dumping area where dozing and leveling work was going on was inadvertently hit and dozed by the dozer, went missing and his dead body was found buried under the slope of the

				freshly dozed overburden dump at about 3.0m down from the crest of the dump”.
62	30-05-2024	Godavarikhani Incline	No.11 1	While an operator of a load haul dump (LHD) machine was standing on dip side of an already loaded and parked load haul dump machine near the side wall of a drift-gallery in an underground coal mine, the said load haul dump machine suddenly started rolling down due to which he was caught and pressed in between side of the pillar and rear end of the load haul dump machine, thus received serious bodily injuries, to which he succumbed on the spot”
63	11-06-2024	Kulda Opencast Project	1	While a tipper driver after exiting from weighbridge parked his loaded tipper by the right side of coal transportation road and was engaged in fixing of tarpaulin by standing at the edge of the tipper’s coal-laden dump box in an opencast coal mine, he lost his balance and fell down from a height of about 3m and was run over by rear right side wheels of another loaded tipper passing nearby, receiving serious bodily injuries to which he succumbed on the spot instantaneously.”
64	28-06-2024	Jayant OCP	1	While a light motor vehicle driven by contractor’s driver with 05 contractor’s employees was travelling along the haul road in an opencast coal mine it suddenly hit and run over by the dumper’s rear right-side wheels near the curved portion of the haul road at about 12m from the junction, inflicting serious bodily injuries to 03 persons of which one person succumbed instantaneously at the spot when other two escaped with minor injuries and one person unhurt”.

65	08-07-2024	Neyveli Lignite Mine-II	1	While a contractual workman engaged for examination and maintenance of belt conveyor at top bench in an opencast lignite (coal) mine was crossing the stationary belt conveyor, suddenly the belt started and he was carried over it to the tail end, where his head was hit and stuck under v-wiper, inflicting serious bodily injuries to which he succumbed on the spot”.
66	17-07-2024	Ramagundam Opencast-ii Mine	2	While a fitter along with Three General Mazdoors was repairing the water pipe line in a trench of about 5.2 m depth made to expose the pipe line buried under loose overburden materials in an opencast coal mine, suddenly, the side of the trench measuring about 2.0 m (long) x 5.2 m (height) x 0.5 to 2.0 m (thickness) parted from the side and slid down, due to which fitter and one of the General Mazdoors got buried under the same which resulted into fatal injuries to them while two others escaped with reportable and minor injury respectively”.
67	27-07-2024	Kusmunda OC Mine	1	While during a heavy rain, six persons on a workplace, were staying in a rest shelter located near the bank of a drain in an opencast coal mine, silt & debris carried along with the flow of water choked the hume - pipes, on the upstream side, resulting in spread of overflow water around the rest shelter; the six persons while trying to escape from the shelter, one of them slipped, lost control and was carried away alongwith the water into sump, at a distance of about 100m, filled with water upto a depth of about 10 m, resulting in his death, who was later recovered after approximately 17 hours and the other five persons escaped unhurt”.

68	06-08-2024	NEYVELI LIGNITE MINE NO.-1A	1	While a contractual workman deployed for signaling discharge boom operator of bucket wheel excavator for positioning the boom over transfer feeder in an opencast lignite (coal) mine, was sleeping on roadway near the transfer feeder, he was run-over by a marching dozer, inflicting serious bodily injuries to which he succumbed instantaneously.”
69	13-08-2024	New Majri UG to OC Mine	1	While an Assistant Mechanic, squatting on the left hand side (LHS) traction chain, was priming to remove air lock from a metallic fuel pipe provided in between Fuel Filter and Fuel Pump of a Dozer parked in the haul road of an opencast coal mine, another Assistant Mechanic sitting on the operator’s seat, started the dozer in forward gear on which dozer moved forward, dislodging the Assistant Mechanic squatting on the traction chain and was run over by the LHS traction chain, inflicting serious bodily injuries that proved fatal instantly.
70	21-08-2024	BLOCK B	1	While 05 persons including contractual employees were engaged for installation of a dewatering pump with base frame on floating pontoon by use of an excavator & two rope slings in an opencast coal mine, suddenly one of the rope slings got slipped, resulted tilting of pump set at one side and then fell on one of the contractual employees ,who received serious bodily injury to which he succumbed instantaneously on the spot while others escaped unhurt”
71	29-09-2024	Chhal Opencast Mine	1	“While a group of 06 Contractual work persons were manually lifting the steel tubular pole of length about 13 mtrs. to place into a pit with the help of rope, near by the Chhal OCM Substation, all of a sudden the steel tubular pole got

				slipped and fell down on one of his Contractual work person neck and got serious injuries. Then he was shifted to hospital, where the doctors declared him brought dead.”
72	30-09-2024	Nigahi OCP	1	While a welder was engaged in welding of monorail support at the roof of a transfer house of under construction coal handling plant of an opencast coal mine and when he gets down for refreshment, inadvertently fell down into the depth of 15.7 mtr on concrete floor from the opening/gap at the side of the discharge chute at same platform, resulted serious bodily injuries to which he succumbed on the way to hospital”.
73	03-10-2024	Gevra OCMine	1	On dated 03/10/2024 at Gevra Project, emulsion pump truck of M/s Shri Krishna Explosive and Accessories bearing registration no. CG 04JA-8450 was engaged for charging of blast hole at patch M/s SMASL patch (NIT-522). After charging of explosive, the said pump truck was returning back at about 03:25PM. On its way from Narabodh to 223 junction, when it was about 200M away from 223 junction it become uncontrolled and went over the right-side berm and toppled opposite to driver side. During this the Technical Service Engineer of M/s Special blast, Shri Gorelal Patel S/o Manglu Ram Patel, aged about 54years got serious injury on the back. He was immediately shifted to NC Hospital Gevra, where he was declared dead.
74	06/10/2024 TF 27/11/2024	Orient Colliery Mine	1	While dressing roof at immediate out-bye junction of a development gallery after blasting in an underground coal mine, a block of shaly coal measuring about 0.9m x 0.6m x 0.15m lying between two roof bolts, suddenly detached from height of 2.6m and hit

				the chest of dresser after slipping along dressing rod, subsequently dresser fell down on his back on blasted coal inflicting serious internal bodily injuries to which he succumbed after undergoing treatment for 52 days at hospital”.
75	07-10-2024	GANGARAMCHACK & GANGARAMCHACK-BHADULIA COAL MINE	8	While unloading of explosives from an explosive van (loaded with booster explosives, electric and electronic detonators, and shock tubes) parked near the site scheduled for blasting at an overburden bench of an opencast coal mine, and primer preparation, carrying them in bunches to the shot holes, and lowering of primer charge into a hole were going on simultaneously, suddenly, a strong blast occurred in the explosive van, resulting in shock waves, air overpressure and ejection of splinters from the damaged aluminium sheeting of the van, which in turn initiated to blast all the primer charges, to which all eight persons engaged in the above operations died on the spot; and one of the three persons present nearby received serious bodily injuries and two received reportable injuries.
76	15-10-2024	Gevra OC Mine	1	While a contractual worker was engaged in cleaning of bottom liner plates inside the silo by standing on ladder in an opencast mine, suddenly a mild steel (MS) plate of size 1m x 1m of 4 mm thickness slid inside along the silo wall from the top of silo opening from a height of about 30 meter and hit the worker on his lower back portion, inflicted serious internal injuries to him to which he was succumbed while undergoing treatment at hospital.”

77	19-10-2024	Rajnager OC Mine	1	“While a person taking shelter along with other three persons in a Bolero vehicle on the top of overburden bench within the danger zone from the place of blasting of an opencast coal mine, a piece of fly rock ejected from the blasting site from the bottom overburden bench, hit a part of roof of the Bolero vehicle and subsequently the roof of the vehicle bent down and hit one person sitting in Bolero vehicle causing serious bodily injury to which he succumbed during shifting to the hospital”
78	18-11-2024	Selected Dhori Opencast mine	1	While a person driving an empty Dumper down the gradient in an open cast coal mine, continuously for more than the stipulated time, lost control and hit OB Dump in which he received serious bodily injury to which he succumbed later."
79	24-11-2024	Magadh OCP	1	While a Dozer Operator, in drunken state, was marching the dozer from coal stock yard to workshop at the end of his shift, he lost his balance at the middle of the haul road and caused the dozer to fell down from the haul road in to the quarry bed at about 25 m, below the haul road, to which he received grievous bodily injuries and succumbed to the injuries on the spot”
80	03-12-2024	Godavarikhani No.7 LEP	1	“While a manager of a belowground coal mine entered inside a stowing bunker installed on the surface to supervise the operation of dislodging stuck up material there, loose material on which he was standing caved in causing him buried under debris and later when he was rescued and sent to the hospital, where he was declared brought dead.”

81	04-12-2024	Jhiria UG Mine	2	While two workmen were engaged for dressing of a newly blasted roof at gallery junction in depillaring panel of an underground coal mine, one of them fell down during dressing of roof and the other attempted to rescue him, suddenly a lump/stone measuring 1.4m x 1.1m x 0.1m size parted from the roof from a height of 3.05m and fell over them inflicting serious bodily injury to both of them to which they succumbed during treatment at the hospital”
82	19-12-2024	Parkashamkhani Opencast Mine	1	While a loaded dumper was being reversed on a dump for unloading overburden material in an opencast coal mine, it rolled back and fell down to immediate bottom bench to a depth of 29 m, inflicting serious bodily injuries to the dumper operator, who succumbed on the way to the hospital.”
83	19-10-2023	Bahula Colliery	1	“While dressing of roof at junction having a loose coal layer of about 0.3m thick in depillaring panel of an underground coal mine was being supervised by Mining Sirdar standing beneath the junction received injuries due to fall of the dressed layer measuring about 5.4m x 4.4m x 0.15 - 0.3m fallen from a height of 3.0 m also inflicting serious bodily injuries to two dressers in which mining sirdar succumbed to injuries.
84	09-10-2023	Jhanjra Project Colliery	1	While, a face crew was escaping from high pressure hydraulic fluid coming out from a valve got broken during operation which was kept on the Bridge Stage Loader and being used for taping hydraulic fluid to erect of OC Prop at Gate roadway in Long-wall Panel, fallen down on the floor containing big lumps of coal inflicting injuries to his left side face and front-temporal reason due to which he succumbed later on.

85	16-01-2023	Gourangdi (A) Colliery	2	While an empty dumper was being parked in the parking yard of an opencast coal mine, another dumper operator, who was present in the parking yard after parking his dumper run over by it and succumbed almost instantly.
86	01-06-2023	Nimcha (R) Colliery	1	While a person deployed at pit bottom of pit no.4 left his post/designated place and transgressed to the exposed space of the empty tubs cage line, he got pressed under the empty cage to which he received serious bodily injuries and succumbed to his injuries.
87	09-07-2023	Tilaboni Colliery	1	While empty tubs were being coupled to each other at the top of haulage plane of haulage roadway of an underground coal mine, it got derailed and hit two persons coming out through haulage roadway resulting serious bodily injuries to them due to which one person succumbed to injury during treatment in the hospital after 3 hours and other person received serious bodily injury.
88	25-06-2023	Amalgamated Konar and Khasmahal OCP	1	While a person was inside the cabin of a Pay Loader near the toe of the of a coal bench, rock mass weighing about one tonne got dislodged from the side of overlying overburden bench and fell from a height of about 70 m on the Pay Loader inflicting serious bodily injuries to the Operator to which he succumbed in a hospital after eight days.
89	20-05-2023	Ena Colliery	1	While a person trying to open the left door of operator's cabin to deal with fire occurred due to leakage of Diesel and Short Circuit at dispensing pump of a diesel bowser standing at haul road of an open cast coal mine, received serious burn injuries to which he succumbed on the spot.

90	15-08-2023	Kujama Colliery	1	While a loaded dumper was moving towards the overburden dump yard in an opencast coal mine, it hit and run over a light motor vehicle (LMV) resulting crushing of the LMV and two persons inside the LMV were fatally injured.
91	13-09-2023	Amalgamated Muraidih Phularitand Colliery	1	While a person entered in the HEMM parking area from where Dumpers were leaving for operation in an open cast mine, suddenly he was hit/run over by reversing Dumper inflicting serious bodily injuries to which he succumbed immediately.
92	22-03-2023	Sendra bansjora	1	While a person was pouring water onto the shovel machine to douse its fire by the hose pipe of fire-tender in an open cast coal mine, suddenly water evaporated from the its hot surface forming hot steam cloud which out spread in the air and steam puff touched his body inflicting burn injury on his body to which he succumbed in the hospital after time of about 20 hours.
93	17-04-2023	Bhowra(South)	1	While a person was attempting to collect a plastic jar, being used to collect water from the discontinued waterlogged quarry of a coal mine for priming of pump, installed at this quarry edge, which had fallen into the water and floating, he went deep into the water & while swimming back towards the edge he failed to swim further & drowned and his floating body was recovered from the waterlogged quarry after about 13 hours of the accident.
94	25-12-2023	Bhowra(South)	1	While a tipper with its raised tipping body was being unloaded near the edge of the overburden dump yard of an opencast coal mine, it fell down from the dump to a depth of about 8m and caught fire, inflicting serious bodily

				injuries to the tipper operator to which he succumbed in the hospital after about two and half hours.
95	01-10-2023	GOVINDPUR PH-II OCP 1		<p>“While a person, riding a motorcycle on a haul road was on his way to the surface, a portion of overburden material measuring about 60 m in length, 8 m in height and 13 m in width got dislodged from the overlying superjacent strata, slid down the gradient, fell on the haul road and buried him, resulting in his death.” As per evidences adduced before me, the cause may be concluded as: Had (i) the workings in the northern side of the mine, overlying the haul road where the accident occurred been kept benched with heights not exceeding 3 m in overburden consisting of alluvium soil or other similar ground and the width thereof not less than three times the height of the bench and in case of overburden of rock formation, with heights not exceeding the digging height or reach of the excavation machine in use and the width thereof not less than the height of the bench, or the width of the widest machine plying on the bench plus two meters or three times the width of the dumper, if dumpers ply on the bench, whichever was more, as required under Regulation 106(4) and Regulation 106(5) of the Coal Mines Regulations, 2017; and (ii) a Scientific Study been made in the mine for determining the method of working, ultimate pit slope, monitoring of slope stability and the mine workings been made accordingly and the slope stability of the workings been monitored as required under Regulation 106(2) of the Coal Mines Regulations, 2017 read with DGMS (Tech.) Circular No. 02 of 2020 and 03 of 2020; this accident could have been averted. This accident is categorized as</p>

				<p>Mining-Statistical as accident occurred within the mine, as the person was employed in the mine, who was on duty and the accident occurred during mining operation as per DGMS (Tech.) Instruction No. 01 of 2017 Dhanbad, dated 04.12.2017.</p>
96	11-10-2023	Jagannath Colliery	1	<p>While a contractual supervisor, supervising tippers movement from the OB face standing at corner of four way junction, approach road to non-working upper bench and tried to stop an empty tipper entering the upper bench for parking at undesignated parking area slipped and got hit by empty tipper, fell down and succumbed to his injuries immediately.</p>
97	21-01-2023	West Bokaro Qr. AB	1	<p>It is concluded that the fatal accident had occurred due to the following reasons: " While the boom cylinder of an excavator in a private coal mine was being removed during maintenance with the help of a crane & web sling, the boom cylinder came out instantaneously to swing abruptly. as such it hit the ladder (working platform) kept for the purpose and fell on the person who tried to hold it causing him serious head injury to which he succumbed on the way to hospital."</p>

98	14-03-2023	Bharatpur OCP	1	While a contractual Tipper was going towards the mine after unloading coal at SILO bunker in an opencast coal mine, the operator lost control of the Tipper negotiating the curve of the road due to over speeding and hit an abandoned building adjacent to the road causing serious injuries to him to which he succumbed almost on the spot.
99	09-03-2023	Garjanbahal OCP	3	While a contractual Tipper operator got down the tipper at the working coal face of an opencast coal mine, the tipper rolled down the gradient and the operator attempting to board the moving tipper caught between tippers when it collided with another tipper parked aside causing serious bodily injury to which he succumbed on the way to hospital.
100	27-10-2023	Topa RO OCP(A) Mine	1	While a 40 T Crane was marching from the mine towards the surface workshop in an opencast coal mine, the crane rolled down the gradient and hit the berm & toppled on the haul road and the operator trapped below the crane causing serious injury to which he succumbed almost on the spot.
101	18-07-2023	Lingaraj OCP	1	While driving a loaded water tanker from water loading point to workshop for scheduled maintenance, he stopped water tanker on haul road having mild gradient (1 in * 22) in an opencast coal mine, climbed down by stair case situated at front side of water tanker, fell down on ground, mean while water tanker moved forward and rolled over him and he succumbed to his injuries immediately.
102	27-09-2023	Magadh OCP	1	While a Weigh Bridge In-Charge was returning to weigh bridge from coal stock of an opencast coal mine on two-wheeler by coal transportation road

				<p>talking on mobile phone, he was hit and ran over by rear right wheel of an empty contractor's tipper entering a coal stock yard causing serious bodily injuries to which he succumbed on the way to hospital.</p>
103	24-07-2023	Lakhanpur OCP	1	<p>While a contractor worker was unwinding a jumper wire of a conductor on a double pole structure of 3.3kV feeder of an opencast coal mine, suddenly the power was charged electrocuting him to which he succumbed on the way to hospital.</p>
104	11-04-2023	Garjanbahal OCP	1	<p>While a hired Bolero vehicle driven by untrained and unauthorized driver with six employees was overtaking a 100T Dumper on the haul road approaching towards a overburden loading face in an opencast coal mine, it was hit, toppled and dragged for about 6m by the Dumper, inflicting fatal injuries to two persons and serious bodily injuries to four persons.</p>
105	13-10-2023	BLOCK B	1	<p>While a contractor tipper driver was driving an empty tipper from dump yard to the working face in an opencast coal mine, the tipper collided head-to-tail with another empty tipper waiting at the junction of haul roads, causing serious bodily injuries to driver to which he succumbed on the way from dispensary to hospital after about one and half hours".</p>
106	17-04-2023	JAYANT OCP	1	<p>While contractual workers engaged for painting of pole of 33 KV overhead line feeder in an opencast coal mine, one of the worker mistakenly climbed onto a pole of other parallel live 33 KV overhead line and came in contact with a live conductor, got electrocuted, causing severe burn injuries, instantly fell onto the ground and succumbed almost instantaneously</p>

107	06-08-2023	Amadand Opencast Mine	1	While a bunch of 05 MS pipes of 8" diameter and 22' length was being unloaded from the truck with the help of wire sling and crane, suddenly an unfastened pipe slipped out from the loop from side edge of the body of the truck and hit a Foreman standing nearby, who was supervising and also helping in pipe unloading operation, causing serious bodily injuries to which he succumbed on the way to the hospital.
108	22-05-2023	Dudhichua OCP	1	While a contractor worker deployed as shift incharge was walking on a haul road of an opencast coal mine, a piece of stone measuring about 1.1m x 0.75m x 0.35m fell from a loaded moving tipper from a height of about 3.2m inflicting serious injuries at his right shoulder to which he succumbed on the way to hospital.
109	28-08-2023	Ramagundam Opencast -iii Mine	1	While a dozer operator was dozing for preparation of drill face on the overburden bench of an opencast coal mine, drill operator approaching the dozing area got hit and dragged by the dozer resulted in to fatal injury to him instantaneously.
110	17-08-2023	Godavarikhani Incline	No.11 1	While a continuous miner operator along with a contractual supervisor went into an un-supported development gallery of an underground coal mine to rectify breakdown of the continuous miner, suddenly, a piece of shaly coal measuring about 1.2 m(long)* 0 - 0.6m (wide)* 0.2m (thickness) parted from the roof and fell over them, resulted into fatal injury to the continuous miner operator and minor injuries to the contractual supervisor.

111	25-07-2023	Adriyala Longwall Project mine	1	While a track mounted electro hydraulic drill machine was being marched in a belowground coal mine, a high pressure hydraulic hose, dislodged from fatigued female swivel end fitting of modified hydraulic system, resulting the hose to whiplash, thereby hitting a person standing in its close vicinity, inflicting serious bodily injuries to him, to which he succumbed on the way to hospital.
112	04-02-2023	Ramagundam Opencast -i Mine	1	While a person was lifting a portable fire extinguisher from its stand by holding its handle and trigger, in a coal handling plant of an opencast mine, the internal CO2 cartridge got activated which energized the fire extinguisher, thus, the pressure built inside ruptured the weak corroded base, thereby causing critical lacerated neck injuries to him, to which he succumbed on the way to hospital.
113	12-01-2023	KOYAGUDEM OPENCAST MINE-I	1	“While a person was standing on the ladder of a diesel bowser truck, stationed at an overburden bench of an opencast coal mine in close proximity of a shovel, suddenly the shovel moved backwards and pressed him against the truck body, inflicting upon him serious bodily injuries, to which he succumbed on the way to hospital.”
114	02-11-2023	Ravindrakhani Incline Mine	No.7 1	while a mechanical fitter was standing adjacent to a haulage track-line along with co-Workers attending to the haulage dismantling work, suddenly he lost balance and fell down, his head hit the haulage track, resulting into head injury (on his left eye brow) and succumbed in the hospital after three and half hours.

115	01-06-2023	NEYVELI LIGNITE MINE NO.-1	1	While a contractual workman was engaged for cleaning the VCB chamber of a 11KV panel without proper shutdown of electric power supply, he accidentally came into the close vicinity of the LIVE terminals, resulted into electrical flashover causing serious burn injuries to him, to which he succumbed during treatment at the hospital.
116	02-07-2023	Integrated Baranj Opencast Mine	1	While a contractual employee engaged for guiding unloading of dumpers carrying overburden to form a platform for coal stock yard near the CHP was taking rest in that area, inadvertently overburden was dumped over him inflicting fatal injuries.
117	23-04-2023	Churcha Mine (RO)	1	While two cable man of continuous miner were handling cable in between the continuous miner and right wall of the pillar in the gallery in belowground coal mine suddenly, a mass of coal measuring about 2.6 m long, 3.8 m high and the thickness varying from 0.05 to 0.20m parted from the unsupported side wall and fell over to one of them inflicting serious bodily injuries to which he succumb on the way to hospital whereas other cable man escaped without any injury.
118	14-10-2023	Gevra OC Mine	1	While a coal consumer truck was plying on a coal transportation road on the surface of an opencast coal mine towards a coal stock yard, suddenly a two wheeler, trying to cross the road, was hit by the truck, causing injuries to the person driving the two wheeler, to which he succumbed while treatment in hospital.
119	10-05-2023	Dhoptala OC(Sasti UG TO OC) Mine	1	While a contractual employee was supervising the levelling work of a proposed haul road by a chain dozer on an overburden bench, he was hit by

				right rear portion of the reversing chain dozer and was crushed under its right crawler chain receiving fatal injuries.	
120	09-01-2023	Kolarpimpri Mine	Opencast	1	While a person was getting down from the tipper in an opencast mine, his hand slipped from the hand rails of the tipper and he fell to about 1.5 m down on the ground causing injury to his vital organs & later died in the hospital after about four hours.
121	13-01-2022	Jayant OCP		1	There was accumulation of spillage coal in between the corridor of ground bunker of CHP on both sides. Contractual workers were engaged for cleaning... During cleaning of spillage coal, one of the workers (deceased) moved from his workplace for some urgent call. Suddenly, the person working there noticed that there was fall of stuck coal from sides of bunker with a loud noise... person was trapped under the fallen coal.
122	15-02-2022	Urimari Open cast Project		1	While a loaded truck was going out from check post barrier, a Security guard inadvertently entered in the close proximity of the truck and run over by its rear right wheels to receive serious bodily injuries to which he succumbed on the spot.
123	17-02-2022	J.K. Nagar(R) Colliery		1	While Shri. Dablu Hari S/O Late Hira Lal Hari was engaged in dressing roof at 9R/11L Junction in 13R fallen coal district, pit no. 3 at J. K. Nagar(R) Colliery in 2nd Shift. On 17/02/2022, a layer of coal measuring 2m x2m x30cm fell over him resulting fatal accident to him.
124	20-02-2022	Rajapur		1	While an excavation was deployed for cleaning and levelling haul road near toe of the bench made in the in-pit waste dump of height 11m & slop 55 degree having fire in an opencast coal mine, a chunk of heated material roll

				down from the bench and fragmented heated lump pieces pierced in the operator cabin by breaking lower portion of the front glass, causing burn injury to the operator who succumbed while undergoing treatment at a hospital after three and half days of the accident.
125	25-02-2022	Ashoke Open Cast Project	1	While an empty truck (road sale) was entering at a parking yard, an Assistant Manager inadvertently entered in the close proximity whilst taking on mobile phone was run over by its rear right wheels and received serious bodily injuries to which he succumbed while undergoing treatment at hospital.
126	07-03-2022	Adriyala Longwall Project mine	3	On 07-03-2022, 1st Shift at about 01:40PM, while supporting disturbed area of a gallery (At 86LN in between RA3D and N2D), suddenly a huge block of coal measuring about 36m(length) X 3.5m(height) X 2.5m(thickness) dislodged from the side of the galley entrapping Six persons. Out of which, Three trapped persons were rescued live and other Three succumbed on the spot.
127	21-04-2022	Tadicherla Open Cast Mine	1	While fixing the lights on the lighting pole Sri Thallapally Kiran slipped and fell down from the height of 2.28 mtrs at RL 855 OB Bench resulting in grade-4 anterior dislocation of C5-C6 vertebrae with cord compression. Subsequently during the course of medical treatment he was died due to brain death and cardio pulmonary arrest after one week.
128	07-05-2022	Bartarai UG Colliery	1	While a female lamp fitter was igniting a flame safety lamp, suddenly the burning match stick dropped on a wiping cloth, partially soaked with fuel, causing fire on it which incidentally initiated fire on her saree

				(due to fall of fired wiping cloth) sustaining serious burn injury which proved fatal after 12 days.
129	13-05-2022	Tawa Mines	2	While they were drilling hole in the roof for bolting, a piece of roof measuring 3.3m x 1.5m x 6" fell on them causing injury, they were taken to the surface by stretcher and to hospital where they were declared dead.
130	18-06-2022	Amalgamated Mines	RKOCP 1	While a motor grader was crossing a junction on the haul road of an opencast coal mine, an unqualified supervisor standing on the haul road was run over by the motor grader, sustained serious bodily injuries and was declared brought dead in the hospital.
131	24-06-2022	Selected Dhoru OC Mine	1	While a excavator was deployed for loading of over burden from an old overburden dump of about 11m in height and sloped at about 72 degrees having fire in remnant rib of coal seam about 2.5- 3.5 m thickness in an opencast coal mine, a chunk of heated material roll down from the highwall side of the bench and broken bot lumps pierced in to the operator cabin by breaking the front glass, causing burn injury to the operator to which he succumbed on the spot.
132	05-07-2022	Rajgamar 4 & 5 Incline		While Shri Radhe Shyam was trying to disengage a piece of coal in chute mouth, using a dressing rod. Suddenly, slack bunker collapsed and come on ground. Consequently, the deceased trapped under collapsed bunker.
133	30-07-2022	Amadand Open Cast Mine	1	While a dumper operator was trying to get down from cabin of dumper which had got stuck at the edge of an opencast coal mine overburden dump, he fell down to a depth of about 8 meter onto the lower side of bench inflicting serious bodily injury to which he

				succumbed in the hospital after 11 days of treatment.
134	11-08-2022	Bhowra(South) Colliery	2	While four workmen were engaged at a pump station at a distance of about 14m from the toe of side of an opencast coal mine, having fiery strata; about 154.72 Cu.m of hot strata dislodged from a height of about 70.40m during heavy rain, emanating cloud of steam and hot ash causing burn injuries to them...
135	08-09-2022	Srirampur No. 1 Incline Mine	1	While hauling loaded tub from 5 ½ LS/7R by 7R direct haulage, the tub attached to the haulage got derailed. In the process of re railing the tub suddenly one set of loaded tubs in 2L north endless ran down uncontrolled and pushed the 7R direct haulage rope towards south resulting in the movement of derailed tub at 5 ½ LS/7R and hit the person causing serious bodily injury.
136	18-09-2022	Satgaram Incline Mine	1	After dressing the roof, the support gang entered to the face for supporting work, the roof measuring 2mtr. (length) X 1mtr. (width) X 0.25 mtr. (Thickness) fell down due to hidden slip resulting fatal injury to Sadagar Bhuia (Driller) and reportable injury to Naresh Roy (Driller).
137	29-09-2022	Dipka No.1A OC Mine	1	While a crew of three mechanics were removing the rear tyre assembly of a crane for replacing the bearing of reduction gear box in an opencast coal mine, its outer disc suddenly thrown out of its position with intense pressure and hit one of the mechanic sitting in-front of it, to which he succumbed instantaneously, whereas other two escaped unhurt.

138	08-10-2022	Kushmunda OC Mines	1	While a tipper was being maintained by maintenance crew in over burden dump area in a coal mine, suddenly one of the maintenance crew members was run over by that tipper during removal of stopper resulting fatal injury instantaneously.
139	06-11-2022	Kalyankhani No.1 Incline Mine	1	At about 4:20pm on 06/11/22 while Sri. Peetla Gopal s/o Giddappa was replacing porcelain insulators on 33kv lines, Sri Bharath Srinivas Electrical Foremen has negligently charged OHT lines due to which Sri P Gopal was electrocuted and fell down from electrical pole.
140	16-11-2022	Kurja UG Colliery	1	While a twin bolter machine (TBM) was installing rock bolts in the widened area of old developed gallery after its widening and heightening of a continuous Miner (CM) panel in an underground coal mine, a support helper went ahead of the temporary Roof Support (TRS) of TBM under the unsupported widened area, where suddenly pieces of rock measuring about 2 "(L) x 2" (W) x 0.5 (T) parted from roof and fell from a height of about 1.9 m on him inflicting serious injury to which he succumbed during treatment in the hospital.
141	19-11-2022	Nichitpur Colliery	1	While a group of eight workmen were repairing a pump at a distance of about 16m from side of a bench... suddenly the berm along the edge of the haul road situated about 45m above, was breached by a pay-loader machine during cleaning of the road, resulting in rolling down of stone pieces... hitting two of the worker by stone pieces.
142	27-11-2022	Dipika Mine No.1A OC	1	While a contractor worker was trying to bring a water pipe from top of the old ramp to bottom bench, slipped from the edge of the ramp and fell on hot ash at

				the bottom edge of ramp on fire, inflicted burn injury, which resulted, into fatality during the treatment at the Hospital.
143	30-11-2022	Bangwar UG Colliery	1	While continuous Miner (CM) machine was being turned from dip to level gallery in a development district of an underground coal mine, a person handling tis trailing cable came in close contact with cutter head and got pressed by it against the col pillar inflicting him serious bodily injury to which he succumbed during treatment in the hospital.
144	31-12-2022	Amalgamated Dhansar Industry Colliery	1	While a dumper operator was engaged to operate a dumper, drove an empty dumper towards top of overburden dump, got down from it at a surface having mild gradient without applying the parking break and run over by the same dumper when it moved backwards uncontrolled; to which he succumbed almost instantly.
