# GOVERNMENT OF INDIA MINISTRY OF ROAD TRANSPORT AND HIGHWAYS

# RAJYA SABHA UNSTARRED QUESTION NO-431

ANSWERED ON-23/07/2025

# CRACKS IN NATIONAL HIGHWAY 66 (NH 66) IN KERALA

#### 431. SHRI HARIS BEERAN:

Will the Minister of ROAD TRANSPORT AND HIGHWAYS be pleased to state:

- (a) whether Government has taken any action on several sections of National Highway 66 (NH 66) currently under construction or being widened across Kerala that have developed cracks and partially collapsed in recent days;
- (b) if so, the details thereof;
- (c) whether the NHAI is using any modern technology, especially in areas where construction over wetland or unstable soil and other coastal areas;
- (d) if so, the details thereof; and
- (e) the action taken by NHAI on companies responsible for the collapsed stretches of NH 66 throughout Kerala, the details thereof?

#### **ANSWER**

# THE MINISTER OF ROAD TRANSPORT AND HIGHWAYS

# (SHRI NITIN JAIRAM GADKARI)

- (a) & (b) Yes Sir. An Expert Committee constituted by National Highways Authority of India (NHAI) inspected the entire stretch of NH-66 in Kerala between 11.06.2025 to 14.07.2025 to assess the adequacy of the protection methodologies adopted/being adopted/ proposed to be adopted for slopes/embankments and other vulnerable locations including the sections, where cracks and damages have occurred recently. The report of the Committee is awaited.
- (c) & (d) For construction of National Highway, latest guidelines, standards & specifications of Indian Road Congress (IRC) are prescribed, which uses /specifies modern technologies.
- (e) The details are annexed.

ANNEXURE REFERRED TO IN REPLY TO PART (e) OF RAJYA SABHA UNSTARRED QUESTION NO. 431 ANSWERED ON 23.07.2025 ASKED BY SHRI HARIS BEERAN REGARDING CRACKS IN NATIONAL HIGHWAY 66 (NH 66) IN KERALA.

Sr. No	Details of collapse/Cracks	Action Taken
1	Ch. 58+035 to Ch. 58+100 (RHS) in Chengala-Neeleshwaram Section of NH-66. Moreover, cracks in Main Carriageway (MCW) and Service Road (SR) has been observed at many locations along the project	work, whichever is later + penalty of 5% of Current value of failed work or 0.5% of Contract value of whole
2	Collapse of retaining wall at Kuriad in Ch. 276+780 and 277+160 (LHS) in Main Carriage Way in the stretch of Ramanattukara Junction to start of Valanchery Bypass section of NH-66.	levy monetary penalty (Rs.20 Lakh) as well as debarment upto 01 year. In addition, Team Leader of the Independent Engineer was also suspended  Project Director of NHAI is suspended and services of
	4 nos. of girder collapsed in Span	site Engineer is terminated.
3	P17-P18 (RHS) in Six Lane of Highway from Thuravoor (Design	Representative of consultant and contractor was suspended and applicable penalty of Rs. 15.4 Lakh imposed to the contractor.
4	Failure/Collapse of scaffolding of Minor Bridge (under construction) at Km.Ch. 497+370(RHS) has occurred in the Start of Kollam Bypass to Kadambattukonam Project.	Concessionaire and Concessionaire has terminated the

\*\*\*\*