GOVERNMENT OF INDIA MINISTRY OF RAILWAYS

LOK SABHA UNSTARRED QUESTION NO.796 TO BE ANSWERED ON 26.06.2019

EFFECT OF HEAVY RAINS ON RAILWAYS

796. SHRI MANOJ KOTAK:

Will the Minister of RAILWAYS be pleased to state:

- (a) whether the Government is aware that heavy rains have severely affected rail services of the Central Railway in Mumbai and if so, the details thereof;
- (b) whether the Government has any plan to provide support to Mumbai's lifeline local trains during the monsoon season;
- (c) if so, the details thereof;
- (d) whether locomotive engine has been modified so that it can move local trains as well as long-distance trains that get stuck on tracks due to water-logging; and
- (e) if so, the details in this regard?

ANSWER

MINISTER OF RAILWAYS AND COMMERCE & INDUSTRY (SHRI PIYUSH GOYAL)

- (a) Rail services of Central Railway in Mumbai have not been affected during this year due to heavy rains, so far.
- (b) and (c) Running of Mumbai local trains, including during monsoon season, is being monitored rigorously. Steps being taken for smooth running of Mumbai local trains during monsoon season include:-
- Control room is being monitored round the clock by officers and running and operating staff is kept on alert and advised to attend office in short notice during flooding.
- 2. Motor points are clamped in flood prone areas.

- 3. Precautionary measures are taken in close co-ordination with Metrological department, BEST and Municipal Authorities and information is given to public through announcement & media.
- 4. Water pumps have been installed at flood prone areas of railway tracks and points have been identified to be clamped in case of heavy rain.
- 5. Patrolmen have been deployed at vulnerable locations by the engineering department.
- 6. Muck Specials are being run at frequent intervals to clear tracks of garbage etc.
- 7. Close co-ordination and liaisoning is done with various Municipal Bodies for arranging local transport and quick disbursal of passengers
- 8. Monsoon precaution booklets have been issued by engineering and safety department, precautionary measures are taken to avoid marooning of rakes by close monitoring.
- 9. Monsoon rakes are formed at various locations to meet unusual occurrences.
- 10. Crowd control at vulnerable locations viz. Foot Over Bridges (FOBs), Station entrance/exits by deputing ticket checking staff and co-ordination with Railway Protection Force (RPF)/Government Railway Police (GRP) staff.
- 11. Proper upkeep and maintenance of ticketing equipments like Unreserved Ticketing System (UTS), Automatic Ticket Vending Machines and Coin-operated Ticket Vending Machines (CoTVMs) to ensure proper condition of ticketing stock and to avoid down time of machines.
- 12. Availability of adequate stock of catering materials and drinking water at all catering stalls, is ensured.
- (d) and (e) No specific modification in diesel locomotives has been carried for this purpose. Diesel locomotives can haul long distance as well as local trains within the existing operational conditions.
